TASK: P752968



WK PKG: PR ET-093-TS-0009

ENG GRP: ETM

TSK LDR:

FLOC: VAB

MLOC: ET-93

STS/FLT: 107 /001

TITLE: SUSPECTED AREAS (1 EACH +Y AND -Y) OF LOW FOAM ON THE

ET/SRB FITTING

OPERATIONS LIST

NUMBER TITLE

TaskBarCode


OperationBarCode

10 SUSPECTED AREAS (1 EACH +Y AND -Y) OF LOW
FOAM ON THE ET/SRB FITTING

20 SUSPECTED AREAS (1 EACH +Y AND -Y) OF LOW
FOAM ON THE ET/SRB FITTING

53700 SCH

H



SUSPECTED AREAS OF LOW FOAM ON ET/SRB FITTING CLOSEOUT

Element/End Item: ET-093

Flow/Usage: 107
Facility: VAB


7.

Design Center Concurrence: MSFC

Category:
OPR: ETM
TTL ORG: SE

N/A

This document does not contain hazardous operations.



The second secon	2968		4.6				
NA SA Space Admi			ROBLEM	PROBLEM REPO	PV-6-38	19 22	<u> </u>
2. Detected During	3. Work Area/Loca	ation/Zone	4. End I	tem Control Nu	mber	- 1	- 3
VISUAL	D2 LEVEL	HB1 VA	B ET-093	-TS- 000 9	1.	. 1	,* .27
5. Part/Program Name			Part/Program N			7. Segal	I/Rev No
ET/SRB FITTING CL	OSE OUT	809	71018422-50	0		N/A	Ì
8. NHA Part Number	9. STS/Eff	10. Repor	rted by				11. Date
80901005000-030	107 T 093	LYNNS	SEELOS AST	706712	VAB OPS 1-119	08	08/0
12. Item 13. Problem C		<u> </u>	- LEDOU INOI	20112	VADOIS I-II3	70	1900
1 Suspected ar	eas (1 each +Y and -Y) o	of low foa	m on the FT	/SDB fitting of	oceout		
	rus (1 euch 1 1 und 1) o	<u> </u>	in on the E1	JAD Hang Ci	oscout.		
					•		<u> </u>
				·			15
						.]) (13)
						1	
							. :
TPS/RSI Insti	d: Yes No C	C/P Instl'd:	Yes	No C/P Pa	rt Number:	1	,
14. Process Escape	15. Constraints 20, 38 A5214, 002 See CRR	8-8-03	16. Crit	17. Eng Grp	18, MR Reqd		Out of Fa
Yes No					Yes No		X Yes [
li l	T1297,002 RUN 3 &	8:4	1 . 2	ETM	P	1	
20 Itam 21 Dispositio	a/Causa/Causatius Astiss		1 3	LIM	ITEMS: 1.0		MS: V
20. Item 21. Dispositio	n/Cause/Corrective Action		1 3	ETIM	ITEMS: C-O	22. Tech	-17
20. Item 21. Dispositio	n/Cause/Corrective Action		1 3,	ETIVI	ITEMS: CO		-17
20. Item 21. Dispositio	n/Cause/Corrective Action		1 3	EIM	ITEMS: 0.0		-17
20. Item 21. Dispositio	n/Cause/Corrective Action		1 3	EIM	TIEMS: CO		-17
20. Item 21. Dispositio	n/Cause/Corrective Action		1 3	EIM	ITEMS: CO		-17
20. Item 21. Dispositio	n/Cause/Corrective Action		1 3	EIM	ITEMS: CO		-17
20. Item 21. Dispositio	n/Cause/Corrective Action		1 3	EIM	TIEMS: CO		-1.7
	n/Cause/Corrective Action		1 3	EIM	ITEMS: CO		-1.7
			1 3	EIM	ITEMS: CO		-17
See uto	? FOR DISPO		1 3	EIM	ITEMS: U.S		-1.7
See ute			1 3	EIM	ITEMS: CO		-17
See uto	? FOR DISPO	11/103		Final Acceptan	ce Date		Contr
See ute	? FOR DISPO	1/7/03					-17
23. Data Code T 0 9 M 9 25. RG Action Regd	7/23/62- 26. Related Report	orts			ce Date		Contr
23. Data Code T 0 9 1 9 25. RG Action Reqd	/23/62-	orts			ce Date	22. Tech	Const
23. Data Code T 0 9 M 9 25. RG Action Regd	7/23/62- 26. Related Report	orts			ce Date	22. Tech	Contr

*****7. :47 35 4 ફર્ષ MANG E- Spage ARU 160

Approval Record

SUSPECTED AREAS OF LOW FOAM ON ET/SRB FITTING CLOSEOUT

Phone: 1-3420

Technical Contact: W. Richards

Category II TOP Only	
This Approval Record is for all Operation No(s) listed below:	
Initial Released Operations:_10	
Added Operations:	
Deleted Operations:	
Replaced Operations:	
Change Index Added USA 8-23-02	
Comments:	
Check Family Type: In Family[] Out of Family[X] NMA[]	

Organization	Name (Printed)	Name (Signature)	Date
ETM	W Richards	NE RIGHT	8-9-02
SE Check	Markewallam		8-12-02
NASA SE		What Theree AHT	
LM ET-LSS	Sur orro	Hoult Otto	8-12-02



ė.,



Approval Record

SUSPECTED AREAS OF LOW FOAM ON ET/SRB FITTING CLOSEOUT

Technical Contact:	W. Richards	P	hone: 1-3420
	Category II	TOP Only	
This Approval Recor	rd is for all Operation No	(s) listed below:	
Initial Released Oper	rations:_10		
Added Operations:			
Deleted Operations:_			
Replaced Operations	:		
Change Index Added]		
Comments:			
Check Family Type:	In Family[] Out of Fa	amily[X] NMA[]	
anizatora s	Name (Bunted)	Name (Signature)	Date is
ETM	Ri Chards	Da RA	
SE Check	Ton Ford	7 m ford	8.19.52
NASA SE	J. RIVERA	pur ex	ile 8-9-02
71 (DM - 00	I.M. Power	DA.	Dela
		Y	



8/19/02 02:05:3 W ()fficial ** PR ::: 093-054009

The following signatures are for the MR disposition only.

Organization	Name (Printed)	Name (Signature)	Date
OPR-MR	DOHN BUE	135	8-19-02
NASA-SE	TRIVERA	Tower Live	7-19-02
ET-LSS	D.M. Power		eliston
MFSC-RO	John Key	John Ken*	8/23/02
QE	DAVIDIN. HOPE	Navid W. Dono	189 8/23/02

* FOR FRED KIENITZ

991 491 114

ा. ए निक्ट

Phone: 1-3420

12/5/02 05:53:38 PM


Technical Contact: W. Richards


Approval Record

SUSPECTED AREAS OF LOW FOAM ON ET/SRB FITTING CLOSEOUT

Category II TOP Only
This Approval Record is for all Operation No(s) listed below:
Initial Released Operations:_10
Added Operations: 20, 30, 40
Deleted Operations:
Replaced Operations:
Change Index Added
Check Family Type: In Family[X] Out of Family[] NMA[]

Organization	Name (Printed)	Name (Signature)	Date 🖠
ETM	W Richards	Micht	12-5-02
SE Check	Tom Ford	70m Tord	n.6.22









Table of Contents:

1.0 INFORMATION
1.3 Operations List
2.0 SAFETY INFORMATION
2.4 Reference Safety Documentation
3.0 STAGING REQUIREMENTS
3.2 Parts, Materials, Equipment, and Special Tools
3.2.5 Shop Support Materials
4.0 PLANNING REQUIREMENTS
5.0 CONFIGURATION ACCOUNTING AND VERIFICATION
List of Contents
.0 CONFIGURATION ACCOUNTING AND VERIFICATION



1.0 INFORMATION

1.3 Operations List

No.	Operation No. Title		OPR	Haz (Y/N)	Dui (Hr	ation s)
10	Defect mapping	ET/ N/A	ETM	N	1.0	
20	Electrical support bracket installation	ET/ N/A	ETM	N	1.0	
30	MRB	ET/ NONE	ETM	N	1.0	
40	Summary/ Closure	ET/ NONE	ETM	N	1.0	

2.0 SAFETY INFORMATION


2.4 Reference Safety Documentation

Number	Rev	Title
KHB 1710.2	LI	KSC Safety Practices Handbook
GSOP 5400	LI	Ground Safety Operating Procedure

3.0 STAGING REQUIREMENTS

3.2 Parts, Materials, Equipment, and Special Tools

3.2.5 Shop Support Materials



12/5/02 05:53:38 PM PR ET-093-TS-0009

OPERATION 10

Part No./Find No. 528-43030-1

Nomenclature lumocolor black pen Qty

Unit EA

4.0 PLANNING REQUIREMENTS

OIR Required Yes [], No [X]

Predecessors:

None


Successors:

None

Configuration Required:

None

5.0 CONFIGURATION ACCOUNTING AND VERIFICATION



Trans.

OPERATION 10 Defect mapping

Shop: ET

Cntrl Rm Console: N/A

OPR: ETM
Zone: N/A
Hazard (Y/N): N
Duration (Hrs): 1.0

Remove P78-3123 Cable brackets

10-1

IF Cables clipped to P78-3123 brackets

Verify

THEN Remove tie wraps supporting cables.



Secure cables to EB fitting using J414 tape or tie wraps.

ELSE Not Perform.




4UG 12 02



ħ


08-09-2009 (a: **** ()fficial * *** :** 095-T\$ 0009




- 10-2 Remove P78-3123 electrical cable support brackets on forward and aft support fittings as follows:
 - Remove tethered bolt from bracket mounting hole, 80911051127-005 fitting mounting hole and wing nut.
 - Loosen bracket clamp at end of 8091051127-002 fitting.
 - Remove P78-3123 electrical cable clamp. Route to storage.

T: 0396 AUG 12 02

*** End of Remove P78-3123 Cable brackets ***



Official 08=09 2002 (3: 3: 24)



Foam (BX-250) along the close-out and NCFI in the cut out are to be flush with the isolator (brown phenolic beneath EB fitting) +0/-.10 inch. Measurements shall be taken with a straight edge laying flush with the isolator.


Mapping in the steps below shall only be for defects greater than -. 10 below the 80971018422-500

10-3 Map areas which do not meet drawing allowances of flush +0/-.10 on figure 10-1. Record Length (Z direction), Width (X direction) and Depth (from the isolator) on Figure 10-1


> SU 2 1 2 702

> > NG 12702 i

- Measure the distance from the center of the EB fitting (XT 2058) to the 10-4 top and the bottom of the EB fitting cut out. Record on Figure 10-1 Maps.
 - 1) Measure find and aft extent of EB fitting T. closeout boundary.



08409-2002 (6: 5:24) PR 157 (1935-TTS:0009 Official NOTE LOW Figure 10-1: Defect Maps EB fitting Closeout Soundan 5,59 Left Hand Side + Z 3".30 EB litting Closeout 4"/× 1/2"D× /2" 1/2"0 × 6/10" W × 6" L Right Hand Side *** End of Figure 10-1: Defect Maps *** O Mark Wollow fates free 8/12/02 PAHZ 8-17-02



08-09-2000 66 528 () fficial * PRETORS-TS-0009

10-5 Perform photo documentation of areas mapped on figure 10-1.

w.o.__1-5


Disc______

STC-T09-FOAM-XXXX-T5

Qw:___

8/12

*** End of Operation 10 ***




OPERATION 20 Electrical support bracket installation


Shop: ET

Cntrl Rm Console: N/A

OPR: ETM
Zone: N/A
Hazard (Y/N): N
Duration (Hrs): 1.0



- 20-1 Install P78-3123 electrical cable support brackets on forward and aft support fittings as follows:
 - 1. Install tethered bolt through bracket mounting hole, 80911051127-005 fitting mounting hole and wing nut.
 - 2. Tighten till all looseness is removed.
 - 3. Position bracket clamp at end of 8091051127-002 fitting with Teflon pad contacting fitting.
 - 4. Tighten till all looseness is removed.



JE 8/23/02

1

143.0

20-2

Attach cables to P78-3123 brackets using ty-wraps.

T: 1-23.02

*** End of Operation 20 ***

15218 1

047.T.J.


OPERATION 30 MRB

Shop: ET

Cntrl Rm Console: NONE

OPR: ETM
Zone: None
Hazard (Y/N): N
Duration (Hrs): 1.0


+Y Side



*** End of +Y Side ***

8/19/02 Date of Control of the contr

-Y Side



*** End of -Y Side ***

Interim Summary

None of the defects meet 80901019010 in-process rework allowances for areas adjacent to a scheduled close-out in that they are greater than 4 inches long and are greater than 25% of the close-out boundary. It should be noted that the defects extend to their deepest at the +Z ends (.3 in below min dwg for +Y side and .2 in below in dwg for -Y side). The ends of the cut out (+Z and -Z) are where the NCFI is the thickest.

The following dispo shall repair the PD 1.0 conditions with the scheduled close-our of the (ET-93-TS-0008 and T1297.002). This shall require MR action since the areas are outside 80901019010 allowances.

*** End of Interim Summary ***

O NA FAIT Richards 8-19-02

QE 4/23/02



MRB ACTION REQUESTED - UNRESTRICTED "USE AS RE

Ref. Item # _1.0.

Reference PD item 1.0, there were several over trims noted on the ET/SRB fitting cut out. None of the defects meet 80901019010 in-process rework allowances for areas adjacent to a scheduled close-out in that they are greater than 4 inches long and are greater than 25% of the close-out boundary.

MR action is requested to accept the close-out of the PD 1.0 NCFI over trims for use as is. Acceptance of this condition is based on the following rationale:

Rationale:

Sufficient NCFI remains to maintain temps within structural limits Low areas are within the envelope of the fairing/closeout

Close-out application performed per the following details (OMI T1297.002) shall encapsulate the PD 1.0 low areas providing additional thermal protection.

- Construct molds per standard procedures (reference OMI T1297.002)
- Vent molds at the center.
- Inject 50cc of foam at the -Z end and at the +Z end.
- Allow excess foam to vent out the center.

This MR action does not invalidate the basis for certification.

This MR action does not impact the Critical Items List (CIL) retention rationale or hazard controls.

Safety, fit or function have not been compromised.

MR Part marking required. Yes [], No [X].

8 21 125 Richards *** End of Operation 30 ***

8-21-02

\$ 8/23lo2

ڃل 29/cz 8/23/1

Ė

OPERATION 40 Summary/ Closure

Shop: ET

Cntrl Rm Console: NONE

OPR: ETM
Zone: None
Hazard (Y/N): N
Duration (Hrs): 1.0

Summary/Conclusion

Ref. Item 1.0, the NCFI on the aft dome was trimmed beyond the drawing allowances. This was evaluated and was found to exceed the 80901019010 allowances for repair of an area adjacent to a scheduled close-out (.75 inch beyond boundary by 4 inches long).

MR action to accept the close-out of the PD 1.0 NCFI over trims for use as is was processed with the following caveat to mitigate the net effect of the low foam.

Foam was applied to the scheduled periphery at either end of the close-out (where the cut-outs were the deepest) instead of in the center to provide for the most foam where needed. This afforded the greatest protection over the low foam areas.

No further rework required.

RC action is requested from ET/SRB ops to instruct technician when trimming around NCFI to not smooth or blend chip outs or irregularities. Further ops is to instruct technicians that NCFI (tank barrel foam) is a very fragile foam and can easily be chipped or torn. This instruction may be accomplished via tailgates. This must be completed by 01/07/03.

Cause: Though this was an unfamiliar task which has only been performed a handful of times in the life of the program, due caution was not exercised when performing the clean-up of the remaining PDL. This was workmanship.

*** End of Summary/ Conclusion ***

40-1 Close this PR.

Qw: Us u Q2

*** End of Operation 40 ***

4